

## **Release note**

### **Manikin Mangement Module V1.0.5**

The following reported bug have been updated for improved functionality

#### **Scenarios**

- System crash after compression trigger
- Time trigger not counting correct

#### **System**

- Configuration page accepts illegal WEP key length
- Invalid network configuration seems to inhibit the network reset button
- Missing text in language files
- Power LED flashes continuously due failure to complete bootup procedure

#### **Control mode**

- Defib symbol not shown in ECG signal field
- ECC rate not correct in debriefing table
- ECC and ventilation rate not shown on manikins
- Visibly of Database entries
- Compression / ventilation levels continuously incrementing
- Jump in ventilation graphs